



One Three Eight sits on the northern side of Cheapside opposite the contrasting landmarks of the historic St Paul's Cathedral and the contemporary One New Change with its highly successful office, retail and restaurant mix.

TRAVEL TIME IN MINUTES TO THE MAIN TRANSPORT HUBS

OLR

BANK

UNDERGROUND

1 MIN

FROM ST. PAUL'S



+ 0

VICTORIA

* *

GATWICK AIRPORT

VIA VICTORIA

≥ 0

KING'S CROSS

ONE THREE EIGHT HOME LOCATION CONNECTIVITY RETAIL LOCAL OCCUPIERS BUILDING SPECIFICATION

≥ 0

LONDON BRIDGE





THE BUILDING

Its prominent curved facade was created in the 1950's in a style that is once again at the centre of high design and this external impact has been complimented by a high quality entrance, progressive office interiors, up to the minute on-site amenities, a level of services that allows efficient and flexible use.



AREA SCHEDULE





FOURTH FLOOR - 'NEW LANDLORD FITOUT'

9,905 SQ FT / 920.2 SQ M



Floor plans not to scale. For indicative purposes only.

OPEN PLAN WORKSTATIONS

97

SEATS

ROOMS

TOTAL WORKSTATIONS

RECEPTIONIST

MEETING ROOMS

8 SEATER

SECOND FLOOR - CORPORATE LAYOUT



OPEN PLAN WORKSTATIONS 30 TOUCHDOWN WORKSTATIONS 23 PHONE BOOTHS TOTAL WORKSTATIONS 55 MEETING ROOMS ROOMS SEATS 10 SEATER 6 SEATER 2 4/5 SEATER 2 SEATER 1 TOTAL 37

CHEAPSIDE

Floor plans not to scale. For indicative purposes only.



SPECIFICATION



ONE THREE EIGHT

CHEAPSIDE

ST PAUL'S

A development by





+44 (0)20 7029 3610

MALCOLM TRICE

M:+44 (0)7791 049 792 E: m.trice@inglebytrice.co.uk JAMES HEYWORTH-DUNNE

M:+44 (0)7779 327 071 E: jhd@inglebytrice.co.uk **JONTY ROBINSON**

M:+44 (0)7748 654 997

E: j.robinson@inglebytrice.co.uk

Ingleby Trice and BH2 give notice to anyone who may read these particulars as follows:

- 1. These particulars are prepared for the guidance only of prospective purchasers. They are intended to give a fair overall description of the property but are not intended to constitute part of an offer or contract.

- 3. Nothing in these particulars shall be deemed to be a statement that the property is in good condition or otherwise nor that any services or facilities are in good working order.
 4. The photographs appearing in this brochure show only certain parts of the property at the time when the photographs were taken. Certain aspects may have changed since the photographs were taken and it should not be assumed that the property remains precisely as displayed in the photographs. Furthermore, no assumptions should be made in respect of parts of the property which are not shown in the photographs.
- 6. Where there is reference in these particulars to the fact that alterations have been carried out or that a particular use is made of any part of the property this is not intended to be a statement that any necessary planning, building regulations or other consents have been obtained and these matters must be verified by an intending purchaser.

- 9. The vendor provides no warranty as to the precise location of the boundaries of the properties.

10. Floor areas are subject to remeasurement December 2023.